



東業德勤測試顧問有限公司
ETS-TESTCONSULT LIMITED

8/F., Block B, Veristrong Industrial Centre, 34-36 Au Pui Wan Street, Fotan, Hong Kong
Tel : 2695 8318 E-mail : etl@ets-testconsult.com
Fax : 2695 3944 Web site : www.ets-testconsult.com

TEST REPORT

Testing of Zinc Plated Screw

Customer Name : Lik Hung Metal Works Ltd. Report Date : 14 January 2010
Address : G/F, 5 Cheung Shun Street, Cheung Sha Wan, Kowloon, Hong Kong Report No. : AGA00003
Sample Description : M5 x 12mm Zinc Plated Screw Lab. Ref. No. : CL/9/G033/01
Date Received : 22 December 2009
Date Tested : 12 January 2010
Page No. : 1 of 1
Test Method : BS 3382 : Part 1 & 2 : 1961


Test Result(s)

Lab. Ref. No.	Customer's Sample Identification	Test Item	Result	Batch Average Thickness of BS 3382 : Part 1 & 2 : 1961
CL/9/G033/01	---	Plating Thickness	0.0141mm	0.0051-0.0064mm

Remarks : The plating thickness of the submitted screw sample was found not in compliance with the requirements of "Zinc on steel components" for zinc plated threaded components in BS 3382 : Part 1 & 2 : 1961.

Tested By : LEUNG, Ka Ming

Checked By : 

Approved By : 
LAU, Chi Leung
Chief Chemist